

January 17, 2020
File No. 15-040.200

Jennifer & Carl Olsen
9916 SW 112th Street
Vashon, WA, 98070

**Subject: Geotechnical Plan Review
Olsen Residence
9916 SW 112th Street, Vashon, Washington**

Dear Jennifer and Carl,

As requested, PanGEO reviewed the geotechnical engineering aspects of the current plans for the above-referenced project. Our review includes the following:

- Architectural plan sheets T1 through T3, DM0.0, DM1.0, and A0.00 through A6.2 dated November 19, 2019 by PROG Architecture + Design, and
- Structural plan sheets S1 through S12 dated November 19, 2019 by TSE Engineering.

In general, it is our opinion that the plans reviewed had incorporated all substantial geotechnical recommendations presented in our geotechnical report dated March 27, 2015.

It is recommended that PanGEO be retained to monitor the construction of geotechnical elements. This is to observe compliance with the design plans, specifications, or recommendations, and to expedite suggestions for design changes that may be required in the event that subsurface conditions differ from those encountered during field exploration.

We trust that the information outlined in this letter meets your need at this time. Please call if you have any questions.

Geotechnical Plan Review
9916 SW 112th Street, Vashon, WA
January 17, 2020

Sincerely,



Michael H. Xue, P.E.
Principal Geotechnical Engineer